

"2 PIVOTS @ 152ND AND MIMOSA ROAD"

WELL INFORMATION

WELL #	LOCATION	USE	DEPTH	STATIC WATER LEVEL	PERMIT GPM	YEAR PERMIT	DISTANCE FROM (F) SECTION LINE	CURRENT STATUS
9434-F	SESE 12/T1S/R60W	IRRIG	125'	69'	1100	1965	1300'(F)S 1300'(F)E	Redrilled with new pump and bowl April 08. 4hr pump test @610 gpm Retested Sept 08 @ 600+/- gpm with some surge.
9404-F	SWSW 12/T1S/R60W	IRRIG	128+/-	34+/-	1100	1965	????'(F)S ????(F)E	Cloudy Title - (May not be able to redrill). Tested Sept 08 250gpm wit some surge. Relined & Replaced Pump & Bowl 1998
63750	NWSW 12/T1S/R60W	DOMESTIC/ STOCK	153'	85'	15	1972	2815'(F)N 75'(F)W	Never used by current owner - Status Unknown